

These are the power supplies to to the buffer/inverters. Each blue rectangle represents 3 wires - +15V, G (0V), and -15V. Some of these wires are shown in this illustration.

